

Rock Springs Pumper

Refurb Specs

BODY

- Rear compartment rust repair
- Cab/chassis undercarriage cleaning and undercoat application
- Interior stainless-steel door panel fabrication
- Latch, closures and weather stripping replacement on rear compartment doors and cab interior doors/panels
- Curbside lower compartment doors out of tread plate fabrication

ENGINE & CHASSIS

- In-frame engine overhaul
- Transmission overhaul
- Front brake replacement
- Odometer gauge replacement
- Corroded battery box replacement

LIGHTING

- Cab interior lighting LED upgrade
- Tank level gauge replacement with LED readout
- Headlight and taillight LED upgrade
- Rear lower LED warning lights addition
- Spotlight LED upgrade
- Step light repair
- Front spotlight repair
- Rear tailboard marker lights repair (secured using silicone)

PUMP

- Pump plumbing and linkage inspection
- Pump test
- Intake and discharge valve rebuild
- Pump panel light LED upgrade
- Water pump front and back seal replacement

PAINT & GRAPHICS

- Gold leaf engine number graphics upgrade (changed to match Rock Springs existing fleet graphics)

UPGRADES / OTHER

- Setcom headset installation with driver wireless set
- Powered and heated side mirrors upgrade
- Diamond plate aluminum hose bed cover fabrication and installation
- Center console map box fabrication and installation
- 12-volt USB charge block installation (inside cab)
- Air system inspection