

Grand County Fire Tower 330

Re-Furb Specs

Prep sand and mast complete truck

Refinish and buff

Paint top half white

Change signage and lettering to match current trucks

Signage and lettering swapped to match fleet

Fixed loose latch on ladder bucket door

Fixed bent rear bumper corner

Made new sign boards

Installed radio