



After **SVI Refurb**



Grand County Aerial Refurb

Existing Chassis

Pierce Arrow XT

Refurbishment Details

- Partial Paint (Top Half Painted White to Match Fleet)
- New Signage and Lettering to Match Fleet
- Loose Latch Repair on Ladder Bucket Door
- Bent Rear Bumper Repair
- Made New Sign Boards
- Radio Installation

Before

