



After **SVI Refurb**



Rock Springs, WY Fire Department Pumper Refurb

Before



Refurbishment Details

- Front Brake Replacement
- LED Cab Interior Lighting Upgrade
- Tank Level Gauge LED Readout Replacement
- Powered and Heated Side Mirrors Addition
- New Interior Stainless-Steel Door Panel Fabrication
- Gold Leaf Engine Number Graphics
- Diamond Plate Aluminum Hose Bed Cover Installation
- Curbside Lower Compartment Doors Fabrication
- Spotlight, Headlight and Tailgate LED Upgrade